SAFETY PRECHECK

Check pins and whipcable on compressor.
Check pins and whipcable on bull hose.
System Air Purge Valve is closed.
Emergency Shut-Off switch set to STOP.
Pot Fill switch set to OFF.
Surface Rinse switch set to OFF.
Check pins and whipcable on blast hose.
Main Pot Shut-Off Valve/"Slurry Valve" closed.



1615 Jefferson Island Road New Iberia, LA 70560 337.359.4365 info@greenerblast.com

greenerblastenergy.com